

# NexSens Vaisala Weather Sensor Mount Quick Start Guide

The WXT510-M is a PVC mount used for attaching a Vaisala WXT-Series weather sensor to a 2" diameter pole with male NPT pipe threads.



## Installation

- 1 Thread the mount onto the top of a 2" NPT pole and turn clockwise until hand-tight. A strap wrench should be used to get an additional ½ to full turn.
- 2 Pull down the rubber set screw cover on the weather station to reveal the set screw.



# NexSens Vaisala Weather Sensor Mount Quick Start Guide

- 3 Note the arrow indicator on the bottom of the weather station. Slide the station onto the mount and rotate it as necessary to align the sensor arrow with True North.



- 4 Use the Allen wrench included in the Vaisala 222109 Bushing and Grounding Kit to tighten the set screw until the weather station fits snugly to the mount.

